

March 5, 1986

CERTIFIED MAIL: EPA: P 447 526 744

MDNR: P 447 526 745

Ms. Bonnie L. Eleder - 5HE-12 Remedial Project Manager CERCLA Enforcement Section U. S. Environmental Protection Agency 230 S. Dearborn Street Chicago, IL 60604

Director Michigan Department of Natural Resources P. O. Box 30028 Lansing, MI 48909 REGETVET 6 1986

U.S. EPA, RESION ? WASTE MANAGEMENT DIVISION MAZARDONS WASTE ENFORCEMENT DRAW

To Whom It May Concern:

Subject: Consent Decree Action 80-73699

I have enclosed copies of plot plans of the Riverview site showing the location of the monitor wells.

No core data was obtained during drilling. According to the Consent Decree, depths were determined by a "visual observation" to verify the interface with the underlying impervious zone. Drilling activities were witnessed by J. Shauver, F. Belobradich, L. Lipinski, and P. Miller.

Well 7 was installed 100 feet east due to access difficulty. Well 7 was eventually abandoned and No. 10 was installed as a replacement updip well. This was done with DNR approval.

In accordance with terms of the Consent Decree which specifies that in sampling wells where more than 6 feet of water are found in the well above interface depth (after 3 days' stabilization) (p. 16.b), a "shallow" well will be installed nearby. This was done June 19, 1985 at the location of Well 6. At this time, Wells 4 (east), 7, 8 and 10 were plugged and pulled since they showed no fluid, leaving 10 wells at 7 locations (at 1, 2 deep, 2 shallow, 3 deep, 3 shallow, 4, 5, 6 deep, 6 shallow, and 9).

If there are any questions, please advise.

Yours very truly,

C. W. Axce

General Manager - Wyandotte


US EPA RECORDS CENTER REGION 5

BASF CORPORATION CHEMICALS DIVISION 1609 Biddle Avenue, Wyandotte, Michigan 48192

Name of Sender: Cost Center No:

BASF

MS. BONNIE L. ELEDER - 5HE-12 REMEDIAL PROJECT MANAGER CERCLA ENFORCEMENT SECTION U. S. ENVIRONMENTAL PROTECTION AGENCY 230 SOUTH DEARBORN STREET CHICAGO, IL 60604



22